

1 Products affected

Product hierarchy no. *				Part no.	SBU	Type / Description	Customer part no.
SBU	PG	PUG	Type				
04	019	200	0000008801	See list below	Circuit Breaker for Equipment	TA35 Rocker 1pole	
04	019	200	0000008802	See list below	Circuit Breaker for Equipment	TA35 Rocker 2pole	
04	019	200	0000008803	See list below	Circuit Breaker for Equipment	TA35 Rocker 3pole	

*SBU (2-digit) / PG (3-digit) / PUG (3-digit) / Type (10-digit)

List of part numbers affected					
4435.0007	4435.0249	4435.0359	4435.0447	4435.0671	4435.0725
4435.0014	4435.0251	4435.0373	4435.0456	4435.0672	4435.0767
4435.0018	4435.0263	4435.0380	4435.0477	4435.0677	4435.0781
4435.0101	4435.0274	4435.0384	4435.0495	4435.0680	4435.0782
4435.0104	4435.0287	4435.0385	4435.0560	4435.0681	4435.0783
4435.0109	4435.0288	4435.0406	4435.0587	4435.0686	
4435.0126	4435.0305	4435.0410	4435.0594	4435.0687	
4435.0146	4435.0324	4435.0411	3-103-074	4435.0702	
4435.0240	4435.0325	3-103-025	4435.0640	4435.0709	
4435.0248	3-102-184	4435.0432	4435.0668	4435.0717	
3-101-078	4435.0344	4435.0439	4435.0670	4435.0719	

2 Type of change

- Change of product specification
- Change on the product label
- Change of quick connect terminals

3 Detailed description of change

According to IEC 60934 circuit breakers of equipment without bimetal are not included within the CBE standard anymore. The listed types lost their VDE approval, explained in the product change notification D10-000-847 on the 20.01.2016.

Therefore SCHURTER has decided to equip all switch types with an additional bimetal.

- 1-pole types will be equipped with one 20A bimetal
- 2-pole types will be equipped with one 20A bimetal
- 3-pole types will be equipped with three 12A bimetals

Please be aware the position of the quick connect terminals will change.

Old product appearance (unprotected pole)	New product appearance (protected pole)

Product Change Notification					PCN TA35		
owner	creation date	release date	released by	change order no	rev	page	D10-011-526
buholzma	2016-12-13	2017-02-10	buholzma	2012161	A	1 of 2	

Old label (from 22.02.2016 until ww 06)		New label	
Old product rating		New product rating	
-		-	
Old product approval		New product approval	
Without VDE marking		With VDE marking	

4 Reason of change

Change of IEC 60934 specification.

5 Release date

The change takes effect in ww 07/2017 (Date code 1707 or higher on label).

6 Impact of change and recommended action

Form	Yes	Changed position of quick connect terminals
Fit	No	No change for dimension
Function	Yes	Overcurrent protection included
Manufacturing	No	No change for manufacturing site
Label	Yes	VDE approval on C00 Types
Packaging	No	No change in packaging

7 Reference Documents / Attachments

Kind of document	Remarks
Web Datasheet	TA35 Rocker 1-pol
Web Datasheet	TA35 Rocker 2-pol
Web Datasheet	TA35 Rocker 3-pol

Product Change Notification						PCN TA35	
owner	creation date	release date	released by	change order no	rev	page	
buholzma	2016-12-13	2017-02-10	buholzma	2012161	A	2 of 2	D10-011-526