

1 Products affected

| Product hierarchy no. * | | | Part no. | SBU | Type / Description |
|-------------------------|-----|-----|------------|----------------|--|
| SBU | PG | PUG | Type | | |
| 04 | 019 | 200 | 0000008801 | See list below | Circuit Breaker for Equipment TA35 Rocker 1pole |
| 04 | 019 | 200 | 0000008802 | See list below | Circuit Breaker for Equipment TA35 Rocker 2pole |
| 04 | 019 | 200 | 0000008803 | See list below | Circuit Breaker for Equipment TA35 Rocker 3pole |

*SBU (2-digit) / PG (3-digit) / PUG (3-digit) / Type (10-digit)

2 Type of change

- New product and packaging label layout for all TA35
- Increased UL rating of 277 VAC for all TA35 1-pole and 2-pole versions with non-illuminated rocker.

3 Detailed description of change

The product and packaging label layout was updated to reflect the increased UL rating of 277 VAC for all TA35 1-pole and 2-pole versions with non-illuminated rocker. The IEC rating for all TA35 remains unchanged.

| Old product label | New product label | Description |
|-------------------|-------------------|------------------------------------|
| | | 1 pole <u>without</u> illumination |
| | | 2 pole <u>without</u> illumination |

The product labels of variants with no change in rating have a new layout:

| Old product label | New product label | Description |
|-------------------|-------------------|---|
| | | 3 pole <u>with/without</u> illumination |
| | | 1 and 2 pole <u>with</u> illumination |
| | | 1 and 2 pole <u>with</u> illumination |

| Product Change Notification | | | | | PCN TA35 | | |
|-----------------------------|---------------|--------------|-------------|-----------------|----------|--------|-------------|
| owner | creation date | release date | released by | change order no | rev | page | D10-030-256 |
| buholzma | 05.02.2019 | 06.02.2019 | wullscdo | 2017093 | B | 1 of 6 | |

| Old product label | New product label | Description |
|-------------------|-------------------|---------------------------------------|
| | | 1 and 2 pole <u>with</u> illumination |
| | | 1 and 2 pole <u>with</u> illumination |
| | | 1 and 2 pole <u>with</u> illumination |

Change of packaging label for all variants:

| | |
|--|-----------------------------------|
| | <p>Old packaging label</p> |
| | |
| | <p>New packaging label</p> |

4 Reason of change

Increased voltage rating of UL approbation of 277 VAC for 1-pole and 2-pole versions with non-illuminated rocker. The IEC rating for all TA35 remains unchanged.

5 Release date

The change will be rolled-out starting ww 07/2019 and lasts until ww 32/2019 (Date code 1907 or higher on label).

| Product Change Notification | | | | | PCN TA35 | | |
|-----------------------------|---------------|--------------|-------------|-----------------|----------|--------|-------------|
| owner | creation date | release date | released by | change order no | rev | page | D10-030-256 |
| buholzma | 05.02.2019 | 06.02.2019 | wullscdo | 2017093 | B | 2 of 6 | |

6 Impact of change and recommended action

| | | |
|---------------|-----|---|
| Form | No | |
| Fit | No | |
| Function | Yes | Increased UL Rating for TA35 1-pole and 2-pole versions with non-illuminated rocker |
| Manufacturing | No | |
| Label | Yes | New layout on product label (incl. new UL rating, where appl.) |
| Packaging | Yes | New layout of packing label (incl. new UL rating, where appl.) |

7 Reference Documents / Attachments

| Kind of document | Remarks |
|---------------------------|--------------------|
| Datasheet | TA35 Rocker 1-pole |
| Datasheet | TA35 Rocker 2-pole |
| Datasheet | TA35 Rocker 3-pole |

List of part numbers affected

| | | | | | | |
|-----------|-------------|-------------|--------------|--------------|-------------|-------------|
| 3-100-114 | 4435.0026 | 4435.0154 | 4435.0282 | 4435.0406 | 4435.0534 | 4435.0668 |
| 3-100-115 | 4435.0027 | 4435.0155 | 4435.0283 | 4435.0407 | 4435.0535 | 4435.0669 |
| 3-100-116 | 4435.0028 | 4435.0156 | 4435.0284 | 4435.0408 | 4435.0536 | 4435.0670 |
| 3-100-132 | 4435.0029 | 4435.0157 | 4435.0285 | 4435.0409 | 4435.0537 | 4435.0671 |
| 3-100-228 | 4435.0030 | 4435.0158 | 4435.0286 | 4435.0410 | 4435.0538 | 4435.0672 |
| 3-100-292 | 4435.0031 | 4435.0158.6 | 4435.0287 | 4435.0411 | 4435.0539 | 4435.0673 |
| 3-100-540 | 4435.0032 | 4435.0163 | 4435.0288 | 4435.0411.GE | 4435.0540 | 4435.0674 |
| 3-100-625 | 4435.0032.6 | 4435.0164 | 4435.0288.GE | 4435.0412 | 4435.0541 | 4435.0675 |
| 3-101-044 | 4435.0033 | 4435.0165 | 4435.0289 | 4435.0413 | 4435.0542 | 4435.0676 |
| 3-101-078 | 4435.0034 | 4435.0166 | 4435.0290 | 4435.0414 | 4435.0543 | 4435.0677 |
| 3-101-156 | 4435.0035 | 4435.0167 | 4435.0291 | 4435.0415 | 4435.0544 | 4435.0678 |
| 3-101-177 | 4435.0036 | 4435.0168 | 4435.0292 | 4435.0416 | 4435.0545 | 4435.0679 |
| 3-101-224 | 4435.0037 | 4435.0169 | 4435.0293 | 4435.0417 | 4435.0546 | 4435.0680 |
| 3-101-310 | 4435.0037.6 | 4435.0170 | 4435.0294 | 4435.0418 | 4435.0547 | 4435.0681 |
| 3-101-521 | 4435.0038 | 4435.0171 | 4435.0295 | 4435.0419 | 4435.0548 | 4435.0682 |
| 3-101-539 | 4435.0039 | 4435.0172 | 4435.0296 | 4435.0420 | 4435.0549 | 4435.0683 |
| 3-101-542 | 4435.0040 | 4435.0173 | 4435.0297 | 4435.0421 | 4435.0550 | 4435.0684.6 |
| 3-101-543 | 4435.0041 | 4435.0174 | 4435.0298 | 4435.0422 | 4435.0551 | 4435.0685.6 |
| 3-101-654 | 4435.0041.6 | 4435.0175 | 4435.0299 | 4435.0423 | 4435.0552 | 4435.0686 |
| 3-101-655 | 4435.0042 | 4435.0176 | 4435.0300 | 4435.0424 | 4435.0553 | 4435.0687 |
| 3-101-733 | 4435.0043 | 4435.0177 | 4435.0300.6 | 4435.0425 | 4435.0554 | 4435.0688 |
| 3-101-734 | 4435.0044 | 4435.0177.6 | 4435.0301 | 4435.0426 | 4435.0555 | 4435.0689 |
| 3-101-843 | 4435.0045 | 4435.0178 | 4435.0302 | 4435.0427 | 4435.0556 | 4435.0690 |
| 3-101-889 | 4435.0046 | 4435.0178.6 | 4435.0304 | 4435.0428 | 4435.0557 | 4435.0691 |
| 3-101-996 | 4435.0047 | 4435.0179 | 4435.0305 | 4435.0429 | 4435.0558 | 4435.0692 |
| 3-101-997 | 4435.0048 | 4435.0180 | 4435.0306 | 4435.0430 | 4435.0559 | 4435.0693 |
| 3-101-998 | 4435.0049 | 4435.0181 | 4435.0307 | 4435.0431 | 4435.0560 | 4435.0694 |
| 3-102-165 | 4435.0050 | 4435.0182 | 4435.0308 | 4435.0432 | 4435.0561.6 | 4435.0695 |
| 3-102-184 | 4435.0051 | 4435.0183 | 4435.0309 | 4435.0433 | 4435.0562 | 4435.0696 |
| 3-102-210 | 4435.0055 | 4435.0183.6 | 4435.0310 | 4435.0434 | 4435.0563 | 4435.0697 |
| 3-102-267 | 4435.0056 | 4435.0184 | 4435.0311 | 4435.0435 | 4435.0564 | 4435.0698 |

| Product Change Notification | | | | | PCN TA35 | | |
|-----------------------------|---------------|--------------|-------------|-----------------|----------|--------|-------------|
| owner | creation date | release date | released by | change order no | rev | page | D10-030-256 |
| buholzma | 05.02.2019 | 06.02.2019 | wullscdo | 2017093 | B | 3 of 6 | |

| | | | | | | |
|-----------|-------------|-------------|-------------|-------------|-------------|-------------|
| 3-102-268 | 4435.0057 | 4435.0184.6 | 4435.0312 | 4435.0436 | 4435.0565 | 4435.0699 |
| 3-102-465 | 4435.0058 | 4435.0185 | 4435.0313 | 4435.0437 | 4435.0566 | 4435.0700 |
| 3-102-466 | 4435.0059 | 4435.0186 | 4435.0314 | 4435.0438 | 4435.0567 | 4435.0701 |
| 3-102-467 | 4435.0060 | 4435.0187 | 4435.0315 | 4435.0439 | 4435.0568 | 4435.0702 |
| 3-102-698 | 4435.0061 | 4435.0188 | 4435.0315.6 | 4435.0440 | 4435.0568.6 | 4435.0703 |
| 3-102-910 | 4435.0062 | 4435.0189 | 4435.0316 | 4435.0441 | 4435.0569 | 4435.0704 |
| 3-103-025 | 4435.0063 | 4435.0190 | 4435.0317 | 4435.0442 | 4435.0570 | 4435.0705 |
| 3-103-028 | 4435.0064 | 4435.0191 | 4435.0318 | 4435.0443 | 4435.0571 | 4435.0705.6 |
| 3-103-029 | 4435.0065 | 4435.0192 | 4435.0319 | 4435.0444 | 4435.0572 | 4435.0706 |
| 3-103-030 | 4435.0066 | 4435.0193 | 4435.0320 | 4435.0445 | 4435.0573 | 4435.0707 |
| 3-103-035 | 4435.0067 | 4435.0194 | 4435.0321 | 4435.0445.6 | 4435.0574 | 4435.0709 |
| 3-103-060 | 4435.0068 | 4435.0195 | 4435.0322 | 4435.0446 | 4435.0575 | 4435.0710 |
| 3-103-061 | 4435.0069 | 4435.0195.6 | 4435.0322.6 | 4435.0446.6 | 4435.0576 | 4435.0711 |
| 3-103-071 | 4435.0070 | 4435.0196 | 4435.0323 | 4435.0447 | 4435.0577 | 4435.0712 |
| 3-103-082 | 4435.0070.6 | 4435.0197 | 4435.0324 | 4435.0448 | 4435.0578 | 4435.0713 |
| 3-103-150 | 4435.0071 | 4435.0198 | 4435.0325 | 4435.0449 | 4435.0579 | 4435.0714 |
| 3-103-183 | 4435.0072 | 4435.0199 | 4435.0326 | 4435.0450 | 4435.0580 | 4435.0716 |
| 3-103-262 | 4435.0073 | 4435.0200 | 4435.0327 | 4435.0451 | 4435.0581 | 4435.0717 |
| 3-103-263 | 4435.0074 | 4435.0201 | 4435.0328 | 4435.0452 | 4435.0582 | 4435.0718 |
| 3-103-296 | 4435.0075 | 4435.0202 | 4435.0329 | 4435.0453 | 4435.0583 | 4435.0719 |
| 3-103-324 | 4435.0076 | 4435.0203 | 4435.0330 | 4435.0454 | 4435.0584 | 4435.0720 |
| 3-103-401 | 4435.0077 | 4435.0204 | 4435.0331 | 4435.0455 | 4435.0585 | 4435.0721 |
| 3-103-402 | 4435.0078 | 4435.0205 | 4435.0332 | 4435.0456 | 4435.0586 | 4435.0722 |
| 3-103-470 | 4435.0081 | 4435.0206 | 4435.0333 | 4435.0457 | 4435.0587 | 4435.0723 |
| 3-103-482 | 4435.0082 | 4435.0207 | 4435.0334 | 4435.0458 | 4435.0588 | 4435.0724 |
| 3-103-746 | 4435.0083 | 4435.0208 | 4435.0335 | 4435.0459 | 4435.0589 | 4435.0725 |
| 3-103-811 | 4435.0084 | 4435.0209 | 4435.0336 | 4435.0459.6 | 4435.0590 | 4435.0726 |
| 3-104-126 | 4435.0085 | 4435.0210 | 4435.0337 | 4435.0460 | 4435.0591 | 4435.0727 |
| 3-104-184 | 4435.0086 | 4435.0211 | 4435.0338 | 4435.0462 | 4435.0592 | 4435.0728 |
| 3-104-228 | 4435.0087 | 4435.0212 | 4435.0339 | 4435.0462.6 | 4435.0593 | 4435.0729 |
| 3-104-291 | 4435.0088 | 4435.0213 | 4435.0340 | 4435.0463 | 4435.0594 | 4435.0730 |
| 3-104-360 | 4435.0089 | 4435.0214 | 4435.0341 | 4435.0464 | 4435.0595 | 4435.0731 |
| 3-104-411 | 4435.0089.6 | 4435.0215 | 4435.0344 | 4435.0465 | 4435.0596 | 4435.0732 |
| 3-104-413 | 4435.0090 | 4435.0216 | 4435.0345 | 4435.0466 | 4435.0597 | 4435.0733 |
| 3-104-425 | 4435.0090.6 | 4435.0217 | 4435.0346 | 4435.0467 | 4435.0598 | 4435.0734 |
| 3-104-446 | 4435.0091 | 4435.0218 | 4435.0347 | 4435.0468 | 4435.0599 | 4435.0735 |
| 3-104-447 | 4435.0091.6 | 4435.0219 | 4435.0347.6 | 4435.0469 | 4435.0600 | 4435.0736 |
| 3-104-448 | 4435.0092 | 4435.0220 | 4435.0348 | 4435.0470.6 | 4435.0601 | 4435.0737 |
| 3-104-783 | 4435.0093 | 4435.0221 | 4435.0348.6 | 4435.0471 | 4435.0602 | 4435.0738.6 |
| 3-104-784 | 4435.0094 | 4435.0222 | 4435.0349 | 4435.0472 | 4435.0603 | 4435.0739 |
| 3-104-932 | 4435.0095 | 4435.0223 | 4435.0350 | 4435.0473 | 4435.0604 | 4435.0740 |
| 3-104-968 | 4435.0096 | 4435.0224 | 4435.0351 | 4435.0474 | 4435.0605 | 4435.0741 |
| 3-104-970 | 4435.0097 | 4435.0225 | 4435.0352 | 4435.0475 | 4435.0606 | 4435.0742 |
| 3-104-971 | 4435.0098 | 4435.0226 | 4435.0355 | 4435.0476 | 4435.0607 | 4435.0743 |
| 3-104-979 | 4435.0099 | 4435.0227 | 4435.0356 | 4435.0477 | 4435.0608 | 4435.0744 |
| 3-105-120 | 4435.0100 | 4435.0228 | 4435.0356.6 | 4435.0478 | 4435.0609 | 4435.0745 |

| | | | | | | | |
|-----------------------------|---------------|--------------|-------------|-----------------|----------|--------|-------------|
| Product Change Notification | | | | | PCN TA35 | | |
| owner | creation date | release date | released by | change order no | rev | page | D10-030-256 |
| buholzma | 05.02.2019 | 06.02.2019 | wullscdo | 2017093 | B | 4 of 6 | |

| | | | | | | |
|-------------|-------------|-------------|-------------|-------------|-----------|-------------|
| 3-105-295 | 4435.0101 | 4435.0229 | 4435.0357 | 4435.0478.6 | 4435.0610 | 4435.0746 |
| 3-105-296 | 4435.0102 | 4435.0230 | 4435.0358 | 4435.0479 | 4435.0611 | 4435.0747 |
| 3-105-327 | 4435.0103 | 4435.0231 | 4435.0359 | 4435.0480.6 | 4435.0612 | 4435.0748 |
| 3-107-495 | 4435.0104 | 4435.0232 | 4435.0360 | 4435.0481 | 4435.0613 | 4435.0749 |
| 3-107-496 | 4435.0105 | 4435.0233 | 4435.0360.6 | 4435.0482 | 4435.0614 | 4435.0750 |
| 3-107-514 | 4435.0106 | 4435.0234 | 4435.0361 | 4435.0483 | 4435.0615 | 4435.0751 |
| 3-107-537 | 4435.0107 | 4435.0235 | 4435.0362 | 4435.0484 | 4435.0616 | 4435.0752 |
| 3-107-557 | 4435.0108 | 4435.0236 | 4435.0363 | 4435.0485 | 4435.0617 | 4435.0753 |
| 3-107-558 | 4435.0109 | 4435.0237 | 4435.0364 | 4435.0486 | 4435.0618 | 4435.0754 |
| 3-107-559 | 4435.0110 | 4435.0238 | 4435.0365 | 4435.0487 | 4435.0619 | 4435.0755 |
| 3-107-677 | 4435.0111 | 4435.0239 | 4435.0366 | 4435.0488 | 4435.0620 | 4435.0756 |
| 3-107-772 | 4435.0112 | 4435.0240 | 4435.0367 | 4435.0489 | 4435.0621 | 4435.0757 |
| 3-107-875 | 4435.0113 | 4435.0241 | 4435.0368 | 4435.0490 | 4435.0622 | 4435.0758 |
| 3-107-900 | 4435.0114 | 4435.0241.6 | 4435.0369 | 4435.0491 | 4435.0623 | 4435.0759 |
| 3-108-593 | 4435.0115 | 4435.0242 | 4435.0370 | 4435.0492 | 4435.0624 | 4435.0760 |
| 3-108-769 | 4435.0116 | 4435.0243 | 4435.0371 | 4435.0493 | 4435.0625 | 4435.0761 |
| 3-108-774 | 4435.0117 | 4435.0244 | 4435.0372 | 4435.0494 | 4435.0626 | 4435.0762 |
| 3-109-122 | 4435.0118 | 4435.0245 | 4435.0373 | 4435.0495 | 4435.0627 | 4435.0763 |
| 3-109-582 | 4435.0119 | 4435.0246 | 4435.0373.6 | 4435.0496 | 4435.0628 | 4435.0764 |
| 3-109-583 | 4435.0120 | 4435.0247 | 4435.0374 | 4435.0497 | 4435.0629 | 4435.0765 |
| 3-109-992 | 4435.0121 | 4435.0248 | 4435.0375 | 4435.0498 | 4435.0630 | 4435.0766 |
| 3-110-877 | 4435.0122 | 4435.0249 | 4435.0375.6 | 4435.0499 | 4435.0631 | 4435.0767 |
| 3-111-336 | 4435.0123 | 4435.0250 | 4435.0376 | 4435.0500 | 4435.0632 | 4435.0768 |
| 3-111-383 | 4435.0125 | 4435.0251 | 4435.0377 | 4435.0501 | 4435.0633 | 4435.0769 |
| 3-111-384 | 4435.0126 | 4435.0252 | 4435.0378 | 4435.0502 | 4435.0634 | 4435.0770.6 |
| 3-111-396 | 4435.0127 | 4435.0253 | 4435.0379 | 4435.0503 | 4435.0635 | 4435.0771 |
| 3-111-583 | 4435.0128 | 4435.0254 | 4435.0380 | 4435.0504 | 4435.0636 | 4435.0772 |
| 3-115-080 | 4435.0129 | 4435.0254.6 | 4435.0381 | 4435.0505 | 4435.0637 | 4435.0773 |
| 3-115-088 | 4435.0130 | 4435.0255 | 4435.0382 | 4435.0506 | 4435.0638 | 4435.0774 |
| 3-119-034 | 4435.0131 | 4435.0255.6 | 4435.0383 | 4435.0507 | 4435.0639 | 4435.0775 |
| 3-119-035 | 4435.0132 | 4435.0256 | 4435.0384 | 4435.0508 | 4435.0640 | 4435.0776 |
| 4435.0001 | 4435.0132.6 | 4435.0256.6 | 4435.0385 | 4435.0509 | 4435.0641 | 4435.0777 |
| 4435.0001.6 | 4435.0134 | 4435.0257 | 4435.0386 | 4435.0510 | 4435.0644 | 4435.0778 |
| 4435.0002 | 4435.0134.6 | 4435.0259 | 4435.0387 | 4435.0511 | 4435.0645 | 4435.0779 |
| 4435.0004 | 4435.0136 | 4435.0260 | 4435.0388 | 4435.0512 | 4435.0646 | 4435.0780 |
| 4435.0005 | 4435.0137 | 4435.0261 | 4435.0389 | 4435.0513 | 4435.0647 | 4435.0781 |
| 4435.0006 | 4435.0137.6 | 4435.0262 | 4435.0390 | 4435.0514 | 4435.0648 | 4435.0782 |
| 4435.0007 | 4435.0138 | 4435.0263 | 4435.0391 | 4435.0515 | 4435.0649 | 4435.0783 |
| 4435.0008 | 4435.0138.6 | 4435.0264 | 4435.0392 | 4435.0516 | 4435.0650 | 4435.0784 |
| 4435.0009 | 4435.0139 | 4435.0265 | 4435.0393 | 4435.0517 | 4435.0651 | 4435.0785 |
| 4435.0010 | 4435.0139.6 | 4435.0266 | 4435.0394 | 4435.0518 | 4435.0652 | 4435.0786 |
| 4435.0011 | 4435.0140 | 4435.0267 | 4435.0395 | 4435.0519 | 4435.0653 | 4435.0787 |
| 4435.0012 | 4435.0140.6 | 4435.0268 | 4435.0395.6 | 4435.0520 | 4435.0654 | 4435.0788 |
| 4435.0013 | 4435.0141 | 4435.0270 | 4435.0396 | 4435.0521 | 4435.0655 | 4435.0789 |
| 4435.0014 | 4435.0141.6 | 4435.0271 | 4435.0397 | 4435.0522 | 4435.0656 | 4435.0791 |
| 4435.0015 | 4435.0142 | 4435.0272 | 4435.0398 | 4435.0523 | 4435.0657 | 4435.0792 |

| | | | | | | | |
|-----------------------------|---------------|--------------|-------------|-----------------|----------|--------|-------------|
| Product Change Notification | | | | | PCN TA35 | | D10-030-256 |
| owner | creation date | release date | released by | change order no | rev | page | |
| buholzma | 05.02.2019 | 06.02.2019 | wullscdo | 2017093 | B | 5 of 6 | |

| | | | | | | |
|-----------|-----------|-------------|-------------|-----------|-----------|-------------|
| 4435.0016 | 4435.0143 | 4435.0273 | 4435.0399 | 4435.0524 | 4435.0658 | 4435.0793 |
| 4435.0017 | 4435.0144 | 4435.0274 | 4435.0400 | 4435.0525 | 4435.0659 | 4435.0794.6 |
| 4435.0018 | 4435.0145 | 4435.0275 | 4435.0401 | 4435.0526 | 4435.0660 | 4435.0795 |
| 4435.0019 | 4435.0146 | 4435.0276 | 4435.0402 | 4435.0527 | 4435.0661 | 4435.0796 |
| 4435.0020 | 4435.0147 | 4435.0277 | 4435.0402.6 | 4435.0528 | 4435.0662 | 4435.0797 |
| 4435.0021 | 4435.0148 | 4435.0278 | 4435.0403 | 4435.0529 | 4435.0663 | 4435.0798 |
| 4435.0022 | 4435.0149 | 4435.0278.6 | 4435.0403.6 | 4435.0530 | 4435.0664 | 4435.0799 |
| 4435.0023 | 4435.0151 | 4435.0279 | 4435.0404 | 4435.0531 | 4435.0665 | 4435.0800 |
| 4435.0024 | 4435.0152 | 4435.0280 | 4435.0404.6 | 4435.0532 | 4435.0666 | 4435.0801.6 |
| 4435.0025 | 4435.0153 | 4435.0281 | 4435.0405 | 4435.0533 | 4435.0667 | 4435.0802 |

| | | | | | | | |
|-----------------------------|---------------|--------------|-------------|-----------------|----------|--------|-------------|
| Product Change Notification | | | | | PCN TA35 | | |
| owner | creation date | release date | released by | change order no | rev | page | D10-030-256 |
| buholzma | 05.02.2019 | 06.02.2019 | wullscdo | 2017093 | B | 6 of 6 | |